

Crook County F & R - Powell Butte Station

Croo_fir03A

Crook County RFPD

Building Type	County	
Fire - RFPD	Crook	
Street		
8900 SW Reif Rd		
City	State	Zip
Powell Butte	OR	97753
Latitude	Longitude	
44.22185	121.02732	
Tracking Code	Inspection Date	
New Building	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	-3.5	-0.5	0	1.6	-0.2	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crook County F & R - Powell Butte Station

Final RVS Score


Final Type Final Score

W1

2.6

FEMA-154 Collapse Potential

Low (<1%)



Crook County F & R - Powell Butte Station

Croo_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2003	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Plan Irregularity Primary

Crook County F & R - Powell Butte Station

Croo_fir03B

Crook County RFPD

Building Type	County	
Fire - RFPD	Crook	
Street		
8900 SW Reif Rd		
City	State	Zip
Powell Butte	OR	97753
Latitude		Longitude
44.22173		121.02731
Tracking Code		Inspection Date
New Building		7/6/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	2	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Crook County F & R - Powell Butte Station

Final RVS Score


Final Type Final Score

RM1

2.3

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2003	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW General Site